




Biradori Bridge Pier Reinforcement







710	200	er u
Ir	iter	loci

ridge pier from water erosion
aido, Japan
2004 to February, 2005
strict Public Works Management Office, Hokkaido
Co.,Ltd.
Method
eet Pile 800mm L=16.0m
Method enables to penetrate a pile into hard difficult subsoil the limited head clearance.

